Digital jumper cable status report

Noel Stanton Kansas State U. 13 Jan. 2003

- Century status
- Basic status
- 2.5 mm connector issues

Century

• 50 cm L2-5 prototypes: 10 built Oct. 2002 R of fine traces typically ~ 40% high. Why?

8 bench-tested @ La Tech or K-State

5 OK

3 have manufacturing defects:

1 open, 2 shorts, 2 intermittent opens Opens & intermittents are in 5 mil traces

2 in use with test stations (Where?) OK?

- Phone meeting with Century engineers 1/6/03 Action items:
 - 1. In-house electrical testing for opens & shorts Century will (soon) quote cost of rig and testing
 - 2. Century will measure line width & thickness of a cable to look for cause of high R
 - 3. Cable with invisible intermittent sent to Century for microscope inspection
- 100 cm prototypes

Quote \$5K for 20

On hold pending resolution of quality control

• Test station cables

Quote \$8.7K for 300


On hold pending resolution of quality control


Basic

- 50 cm L2-5 prototypes (10)
 10 bench-tested @ K-State June 2002
 2 open/intermittent (pad/ablation problem)
 3 subsequently failed in use @ FNAL
 6 open/intermittent lines (connector joints)
 1 short (near/at end, not seen)
- 50 cm L0-1 prototypes (10) ~ 6 Sep 02 No bench-testing, put into test station use No reported failures (but no systematic records)
- 100 cm L0-1 prototypes (20)
 Manufacturing difficulties, 3 tries
 Try #1: NG
 Try #2: Yield of 5
 To Bob Jones 3 Dec 02. Now at ...?
 Try #3: Yield of (at least) 15
 Will go for ablation this week (new mask)
- Test station cables
 Quote \$14K for 150
 FNAL encouraged to submit PO

2.5 mm connectors

- Plan:
 - 2.5 mm receptacle on hybrid end
 - 3.0 mm plug on outer end
- 2.5 mm footprint too wide for present ablation $(\pm 4.0 \text{ mm from centerline vs} \pm 3.4 \text{ mm})$
- New mask to be made by ALT (inner end only) Will extend 0.5 mm beyond gold pad edge (Present mask ends 0.5 mm inside pad edge)





- 15 Basic 100 cm cables to use this mask Time scale for new mask/ablation ~ 2 weeks
- Mechanical issues (insertion/extraction force; tool) Hans J. has volunteered to investigate